Pla 49 R7.955 3/20/2018 Broadside v1 EB Joeger Rd approaching Rte 49 intersection, failed to yield, struck by v2 SB 49 #2 Ln 70 mph

v1 SB 49 #1 85 mph heavy rain. V2 NB #2 60 mph. v1 hydroplane crossed center into NB struck
front v2.

Pla 49 R8.170 1/1/2020 Broadside v2 NB 49 #2 60 mph. v1 WB on private driveway made a left turn onto SB 49 was struck by v2.

FATAL COLLISION REPORT 01/01/2015 TO 01/30/2020

Description

v1 DUI SB 49 50 mph approaching Holcomb Dr. v2 motorcycle NB approaching Cherry Crk Rd. v1

v1 SB 49 driving erratically, spun sideways crossed centerline into NB and was struck by v2.

v1 DUI SB 49 N of Mother lode Rd unknown speed, onto Rt shoulder then on dirt and collided

v1 SB 49 at Pingree Rd 60 mph. For unknown reason, v1 drifted and crossed into NB and sturck

Type of Collision

Hit Object

Broadside

Hit Object

Head-on

of v3.

with a tree.

left front v2 in #1 NB Ln.

Number

Co Rte

Nev 49

Nev

Nev 49

Nev | 49

9

10

11

49

PM

5.795

6.45

6.66

9.49

Date

9/26/2019

2/7/2015

1/21/2017

1/12/2017

3	Pla	49	R8.170	1/1/2020	Broadside	v2 NB 49 #2 60 mph. v1 WB on private driveway made a left turn onto SB 49 was struck by v2.
4	Pla	49	R8.973	9/25/2018	Broadside	v1 NB 49 in Lt turn Ln approaching Lorenson Rd. v2 SB #1 69 mph. v1 failed to yield and made
						unsafe turn and struck by v2.
5	Dla	49	R9 250	6/16/2017	Head-on	v1 NR 49 #1 Ln 50 mph, undetermined reason, crossed into SR #1 Ln and struck front v2

	1 10	45	1131230	0/10/2017	ricad or	VI 145 45 11 En 36 mph. undetermined reason, crossed into 35 11 En and struck front V2.
6	Pla	49	R9.510	12/4/2019	Sideswipe	v1 NB 49 high speed, angry, Diabetic, N of Dry Creek Rd, entered median and then #1 SB Ln and sturck v2 SB.
						v1 erratically NB 49 50 mph approaching Combie Rd. v2 stopped in Lt pocket. V3 WB Combie Lt
7	Nev	49	2 16	4/9/2015	Sideswine	nocket. Signal turned green, v3 drove forward, V1 stuck v2 mirror then struck front driver side

tire hit curb, lost control into path of v2 and stuck v2. p2 ejected.